

FOR CENTRAL OFFICE USE ONLY

ESTABLISHMENT NUMBER

				OOL C	The second representation of		
Establishment Name Super 8 Motel				Name Owner General Manager			
Physical Address 930 Valley Creek Drive	City Farmington				Zip 63640		
Mailing Address Same as physical address		City				Zip	
County This inspection is a(n) 187	6-0344	No. of Stories 2	No. of Rooms 62		nt lodging licens		
Rooms Inspected:	Water Supply	Variable and the special control	CONTROL TO MESSAGE TO THE SECOND	Wastewater		rote: Company rough and a bord	
100 131 133 14E 30E 310 331 333	☐Private	Public Private Public					
109, 121, 122, 145, 205, 219, 221, 222,	Water sample	ample taken ☐Yes ☑No Regulated by: ☐DHSS ☑DNR					
*	Swimming Pools/Spas (check all that apply)						
	Indoor pool						
Diseas shook if the following	□ N/A	pool== Opa	_ rooman	901 111011 2000	equal o loce		
Please check if the following local ordinances apply	New Lodging Estab						
Fire Safety Electrical Wiring	Smoke detectors hardw		The second secon				No L N/A
Plumbing	Fire alarm system installed						
Swimming Pools/Spas Fuel Burning Appliances Sprinkler system installed		ed Ye	es 🔲 No 🔲				No No N/A
Fuel Burning Appliances Sprinkler system installed						_	_
Based on an inspection this day, the items marked "Out" below identify noncompliance in operations or facilities which must be corrected prior to issuance or							
renewal of your lodging license. Failure to comply with any time limits for corrections specified in this notice may result in revocation of your lodging license and/or prosecution. Owners may request a hearing before the Department Director upon filing a written request within ten days after receipt of this notice.							
(RSMo 315.005-065, 19 CSR 20-3.050)							
	t=Not In Compliance, e	xplain on additi	onal page(s)	NO=Not O	bserved N	I/A=Not Applica	able
Section A & B: Water Supply & Wast			Section E: Fir		Mark Mark Indian and Array of the		Out NO N/A
1. Approved source, construction and or	peration	× 1	I. Textiles, han	gings and mirrors	3	×	
Complies with water quality standards		× 2	Fire extinguisher type, inspected, and location				
Chlorinator maintained and operated properly			3. Vertical openings fire-rated, self-closing				×
4. Wastewater operation and maintenance			4. Doors, self-closing and fire-rated				×
Section C: Sanitation/Housekeeping 1. Walls, floors and ceilings in good repart 1. Walls, floors and ceilings in		5. Smoke detectors hardwired, installed, good repair 6. Evacuation route and plan, installed, available					
1. Walls, floors and ceilings in good repair 2. Housekeeping practices and furnishings			7. Stairs and ramps, maintained, storage				
3. Towels and bed linens clean			8. Means of egress, number, maintained				
4. Mattresses and box springs clean			9. Handrails and balconies maintained and appropriate				
5. Pest control procedures			Section F: Swimming Pools/Spas				
6. Ice machines, scoops, liners clean & protected			1. Fence, gate adequate, proper closure mechanism				
7. Garbage storage and disposal	entrolled ×		E. Boundary line, poor depair properly marked			×	
8. Premises maintained, plant growth co			e. Deck le clear and in geed repair				
Food Inspection conducted according to 19CSR20- 9. Food, equipment and single service/use			4. Lifesaving equipment adequate, good repair 5. Pool clarity, pH, disinfectant, & temp. maintained				=
10. Food protected from contamination	×		6. Steps, ladders, and handrails installed, good repair				
11. Facilities to wash, rinse and sanitize			7. Adequate ventilation				
12. Handwashing facilities/hygienic practices			e. Electrical catiote, proper protection a dictance				
Section D: Life Safety			9. Records maintained and signs posted				
Combustible/toxic items usage and storage Building maintained to assure safe conditions			10. First aid kit available 11. Lighting adequate and in good repair				
3. CO detectors hardwired, installed, good repair			Section G: Plumbing/Mechanical				
4. GFCI, outlets & switches installed, good repair			1. Equipment adequate, good repair				×
5. Exit signs installed, good repair		2	2. Ventilation adequate, plumbing, restrooms				
6. Emergency lighting installed, good repair			3. T & P relief valves adequate, good repair				
7. Electric panel protected, labeled, good repair			4. Relief valve discharge pipes installed, adequate				
Required Annual Third Party Inspections			5. Backflow, air gaps, no cross connections				
1. Fire Alarm System 2. Sprinkler System			Section H: Heating & Cooling 1. Unvented fuel-burning appliance/space heater				
3. Local Fire and Building Codes/Ordinances			Onvented ruel-burning appliance/space neater Fire resistant room or sprinkler head			═╢╠═╣╠╧╣	
4. Current Boiler/Pressure Vessels MDF	PS			John or opinikle			
Certification	×			eating/cooling ur		×	
5. Backflow Device(s) Test	×	4	I. Ventilation of	f appliances and	utility rooms	×	
6. Liquid Propane Leak Test			5. Operation and condition adequate				
INSPECTED BY (PRINT NAME and SIGN)		EPHS	NUMBER A			TELEPHONE	
Donovan Kleinberg				Francois County		(573)431-1	
LICENSING YEAR				ATE INSPECTED		FOLLOW UP DATE	
20 22 / 20 23 APPROVED YES) N	/lay 27, 2022		June 14, 20	122
RECEIVED BY (PRINT NAME AND						PAGE 1 OF	2
Nirav Patel (6-16)	Distribution: White/	Owner Canary	Central Office	Pink/Local Office			E9.02

MISSOURI DEPARTMENT OF HEALTH & SENIOR SERVICES BUREAU OF ENVIRONMENTAL REGULATIONS AND LICENSURE LODGING ESTABLISHMENT INSPECTION REPORT (COMMENTS PAGE)

2 of 2

Establishment Name: Super 8 Motel Physical Address: 930 Valley Creek Drive

City: Farmington

SECTION REFERENCE

OBSERVATIONS AND ADDITIONAL COMMENTS

LAUNDRY

C1 - There were water stains visible in the ceiling of the laundry room. Floors, walls and ceilings shall be in good condition.

Room 109

C2 - There was minor mold growth detected inside the AC vent. Proper housekeeping procedures shall be employed.

C3 - The sheets had cigarette burns in them. Bed linens shall be in good condition.

Room 12

No violations found.

Room 122

G1 - The filter for the AC unit was found to be broken. Mechanical equipment shall be kept in good repair.

E5 - The smoke detector did not have a battery inside of it. Smoke detectors shall be powered and function properly.

Room 145

G1 - The filter for the AC unit was found to be broken. Mechanical equipment shall be kept in good repair.

C1 - There was a gouge in the wall by the sofa. Walls, floors and ceilings shall be kept in good condition.

West Side Storage Room on 1st Floor

C1 - There was a hole in the ceiling inside the attached closet. Floors, walls and ceilings shall be in good repair.

Central Storage Room on 1st Floor

C10 - There was a box of cereal stored on the floor. CORRECTED ON SITE by moving the box off the floor.

Central Maintenance Room

E5 & D3 - The smoke/CO detector did not have batteries and was detached from the ceiling. Smoke detectors and CO detectors shall function properly.

Room 222

C2 - The alarm clock for this room was filled with dust or lint. Proper housekeeping procedures shall be used.

Room 221

D4 - The GFCI outlet did not have power to it and the button to test it was broken exposing the outlet behind it. GFCI outlets shall be in good repair and function as intended.

Room 219

E5 - The smoke detector did not work when tested. Smoke detectors shall be functional.

HALLWAY

C1 - There was a rip in the wall paper outside the door of room 229 in the hallway. Floors, walls and ceilings shall be maintained in good repair.

Room 234

No violations were found.

Central Storage Room 2nd Floor

E3 - The laundry chute was left propped open with a rod. Vertical openings such as laundry chutes shall be self-closing and kept closed when not in use. CORRECT ON SITE by closing.

Room 237

C3 - There were cigarette burns on the sheets. Bed linens shall be in good condition.

D4 - The GFCI outlet did not break the circuit when tested. GFCI outlets shall function properly.

Room 205

C2 - There was mold growth found inside the air vent in the bathroom. Proper housekeeping procedures shall be employed.

POOL

Chlorine was 3.0 and PH was 7.2.

Third Party Inspections needed: City of Farmington Fire - Still needed.

Fire alarm - March 10, 2023

Backflow - March 23, 2023

Boiler - 2023

Date:

Date:

Fire Extingushers - March 10, 2023

Donovan Kleinberg

May 27, 2022

Received by:

Inspected by

Nirav Patel

May 27, 2022

MO 580-0883 (1-09)