

FOR CENTRAL OFFICE USE ONLY

ESTABLISHMENT NUMBER

-acccv.				UOL	CINE I				
Establishment Name Rosener's Inn	Name Sowner General Manager Deepak, Patel								
Physical Address 3411 Rosener Road		Park Hills				^{Zip} 63601			
Mailing Address Same as Physical		City				Zip			
County This inspection is a(n) 187	1-4241	No. of Stories 1	No. of Rooms	Is the curre	nt lodging licen No 🗖 N/A- nev	se displayed w	?		
Rooms Inspected:		Water Supply		and the Market war for the state of	Wastewater			- 3	
	☑ Private								
116, 118, 112, 106, 105, 104, 103, 142	Water sample					☑DNR			
		Swimming P							
						4 0000) <i>(</i> -	_ , 🖂	
		Indoor pool		pool Spa	a 🖵 Pool lar	ger than 2000) square tee	et 🗀	
Please check if the following local ordinances apply	New Lodging Estat	olishments	■ N/A						
Fire Safety Electrical Wiring	Smoke detectors hardy	vired 🔲 Ye	es 🗆 No 🗖 N	N/A Swimmin	g Pool Certified	☐ Yes ☐	No 🔲 N//	A	
☐ Plumbing	Fire alarm system insta	alled Ye							
Swimming Pools/Spas			Permit Yes			☐ Yes ☐	No		
Fuel Burning Appliances	Sprinkler system install	led LY	Yes No N/A Historical Building Yes			Yes L	No N/A		
Based on an inspection this day, the ite	ms marked "Out" below	identify noncomp	liance in opera	tions or facilities	s which must be o	corrected prior t	o issuance o	ır	
renewal of your lodging license. Failure	to comply with any time	limits for correct	ions specified i	n this notice ma	av result in revoca	ition of your lod	aina license	1.5	
and/or prosecution. Owners may reque									
(RSMo 315.005-065, 19 CSR 20-3.050)									
	t=Not In Compliance, e				Observed N	/A=Not Applic	able	end a tra	
Section A & B: Water Supply & Wast			Section E: Fire		e i percenti de propose de la composició d Composició de la composició de	<u>In</u>	Out NO	N/A	
1. Approved source, construction and o				gings and mirro		×	▼		
Complies with water quality standards			2. Fire extinguisher type, inspected, and location					=	
Chlorinator maintained and operated properly Wastewater operation and maintenance			Vertical openings fire-rated, self-closing Doors, self-closing and fire-rated				×		
Section C: Sanitation/Housekeeping		5. Smoke detectors hardwired, installed, good repair			nair X		\vdash		
Walls, floors and ceilings in good rep					nstalled, available	1	a a i		
Housekeeping practices and furnishing				mps, maintaine		×			
3. Towels and bed linens clean			8. Means of egress, number, maintained						
4. Mattresses and box springs clean		9. Handrails and balconies maintained and appropriate							
5. Pest control procedures	X		Section F: Swi	imming Pools/	Spas	telono, en el Rabie		394	
6. Ice machines, scoops, liners clean &		1. Fence, gate adequate, proper closure mechanism					×		
7. Garbage storage and disposal			Boundary line, pool depth properly marked					×	
8. Premises maintained, plant growth controlled x Food Improve the controlled A 2005 P30 4 2005			3. Deck is clean and in good repair			.		×	
Food Inspection conducted according to 19CSR20-1.025			4. Lifesaving equipment adequate, good repair					×	
9. Food, equipment and single service/use			5. Pool clarity, pH, disinfectant, & temp. maintained					×	
11. Facilities to wash, rinse and sanitize			6. Steps, ladders, and handrails installed, good repair 7. Adequate ventilation				×		
12. Handwashing facilities/hygienic prac			8. Electrical outlets, proper protection & distance					×	
Section D: Life Safety		9. Records maintained and signs posted							
1. Combustible/toxic items usage and s	torage ×		10. First aid kit available					×	
2. Building maintained to assure safe co			11. Lighting adequate and in good repair					×	
3. CO detectors hardwired, installed, go				ımbing/Mechai					
4. GFCI, outlets & switches installed, go				dequate, good r		×			
5. Exit signs installed, good repair			2. Ventilation adequate, plumbing, restrooms 3. T & P relief valves adequate, good repair				×	\dashv	
6. Emergency lighting installed, good re7. Electric panel protected, labeled, good						**	×	-	
Required Annual Third Party Inspect				gaps, no cross	installed, adequa	ite	 	_	
Fire Alarm System				ating & Cooling				327700-1	
Sprinkler System					ance/space heate	r ×			
3. Local Fire and Building Codes/Ordina	ances			room or sprink				×	
4. Current Boiler/Pressure Vessels MDI								_	
Certification				eating/cooling ι				_	
5. Backflow Device(s) Test	×		1. Ventilation of	appliances and	d utility rooms	×			
6. Liquid Propane Leak Test				d condition ade	quate		×		
INSPECTED BY (PRINT NAME an	d SIGN)		NUMBER A			TELEPHONI			
Donovan Kleinberg	· Kill	1686			ty Health Center	(573)431-1			
LICENSING YEAR		ES NO		ATE INSPECT		FOLLOW UF	DAIE		
20 <u>23</u> / 20 <u>24</u> APPROVED YES) M	1ay 31, 2023	3	TBD			
RECEIVED BY (PRINT NAME AND						PAGE 1 OF	3		
		up dota!!! !-	الحدامة ما	ator					
This report was emailed to Dee	pak Patel, a follow- Distribution: White		Central Office	ater. Pink/Local Offic	Δ		E9.02		
1010 000-0000 (0-10)	Pignipanon. White	owner carrary/	Ochida Onice	I IIIK/LUCAI UIIIC			∟ 5.0∠		

Time In: 10:00 AM

Time Out: 11:30 AM

i age

of 3

Rosener's Inn

Physical Address:
3411 Rosener Road

City:
Park Hills

SECTION REFERENCE

OBSERVATIONS AND ADDITIONAL COMMENTS

GENERAL FACILITY

- C5 The majority of sleeping rooms had pests such as living and dead cockroaches, spiders, flies and beetles. Pest control procedures shall be employed.
- C3 The majority of sleeping rooms had stained, burned or torn linens and sheets. Linens shall be in good condition.
- E2 The fire extinguishers for the facility had inspection tags of May 2022, considering this was the last day of May 2023 and no mention of an inspection for the fire extinguishers was made it is presumed they will be expired come June 1. Fire extinguishers shall be inspected annually.

LOBBY

- C5 Dead beetles were found throughout the lobby behind the ice machine and near the gaming machines; live cockroaches and spiders were found inside the lobby bathroom sink. Pest control procedures shall be employed.
- C2 The microwave inside the lobby was found to be dirty and in bad condition. Furnishings shall be in good repair.
- E2 The fire extinguisher in the lobby closet was found to be low on pressure. Fire Extinguishers shall be in good condition and ready for use if needed.
- C1 There was a hole in the ceiling inside the closet which resulted in a large accumulation of spilled insulation on the floor. Ceilings shall be in good repair.

LAUNDRY AREA

- C9 Toilet paper was found stored on the ground. Single service items and supplies shall be stored off of the ground.
- C5 Dead bugs were found on the floors. Proper pest control procedures shall be employed.
- E4 The laundry room door was found propped open. Fire doors shall be kept closed when not in use.

ROOM 116 - CLEAN

- C1 There was a hole in the wall at the bathroom door. Walls shall be in good repair.
- C2 Debris was found inside the drawers, stains were found on the window curtain, the ceiling light in the bathroom did not function and the microwave was in poor condition. Proper housekeeping procedures shall be employed and furnishings shall be in good condition.

ROOM 118 - CLEAN

See general facility violations.

- C2 There was a loose screw in the lower door weather stripping. Furnishings shall be in good repair.
- C1 There was a hole in the wall behind the bathroom door. Walls shall be in good repair.
- D4 The outlet cover for the outlet between the two dressers was very loose. Outlets shall be in good condition.

ROOM 112 - CLEAN

See general facility violations.

- G2 The fan in the bathroom did not operate. Ventilation in bathrooms shall be adequate.
- C2 The dresser was found with debris inside the drawers and uncleaned spills on the top. Proper housekeeping procedures shall be employed.

ROOM 106 - CLEAN

See general facility violations.

ROOM 105 - CLEAN

See general facility violations.

C2 - The cover for the fan in the bathroom had fallen off. Furnishings shall be in good condition.

ROOM 104 - CLEAN

See general facility violations.

ROOM 103 - CLEAN

See general facility violations.

C2 - A stain was found on the lampshade. Proper housekeeping procedures shall be employed.

ROOM 142 - CLEAN

See general facility violations.

- C2 There was debris inside the toilet. Proper housekeeping procedures shall be employed.
- D2 There was an empty light socket in the vanity. Safe conditions shall be maintained.
- C1 The outside door frame was covered in peeling paint and appeared damaged. Walls shall be in good condition.

11 L

ROOM 141 - CLEAN

See general facility violations.

Inspected by:	Donovan Kleinberg	Date: May 31, 2023
Received by:	This report was emailed to Dee	Date: June 1, 2023



MISSOURI DEPARTMENT OF HEALTH & SENIOR SERVICES BUREAU OF ENVIRONMENTAL REGULATIONS AND LICENSURE LODGING ESTABLISHMENT INSPECTION REPORT (COMMENTS PAGE)

3 of 3

Establishment Name: Rosener's Inn

Physical Address: 3411 Rosener Road

City: Park Hills

0014405 01541

OBSERVATIONS AND ADDITIONAL COMMENTS

ROOM 125 - CLEAN

G2 - The fan in the bathroom was missing. Adequate ventilation in bathrooms shall be provided.

ROOM 127

See general facility violations.

SECTION REFERENCE

GUEST LAUNDRY

- C2 Debris was found on the walls. Proper housekeeping procedures shall be employed.
- D2 The dryer lint traps were found to be very full. The building shall be maintained to have safe conditions.

SOUTH BUILDING MAINTENANCE ROOM

- G3 -There was no discharge pipe for one of the water heaters. Discharge pipes shall be present to drain water down by gravity and made of a sturdy material.
- G5 A cross connection/backflow issue was noted as the hot water heaters were observed cross connected with a metal hose which itself was connected to a open ended garden hose. No cross connections shall exist.

EAST BUILDING MAINTENANCE ROOM

- D2 There were several empty light sockets inside the room. Safe conditions shall be maintained.
- C5 Live roaches were observed. Proper pest control procedures shall be employed.
- C1 There was a hole in the ceiling by the water heaters with a large pile of insulation below it. Ceilings shall be in good condition.
- G4 -There was no discharge pipe for one of the water heaters. Discharge pipes shall be present to drain water down by gravity and made of a sturdy material.

NORTH BUILDING MAINTENANCE ROOM


G4 - A discharge pipe with 2 90 degree bends was observed on one of the water heaters. Water heater discharge pipes shall have no more than one 90 degree bend.

OUTSIDE

- H5 The outer grate of the air conditioner for room 123 was found broken. Heating and cooling equipment shall be in good condition.
- C8 The outside sign had a large tarp hanging from it. The premises shall be maintained in clean and good condition.

NOTE - This facility shares water with the restaurant Lady Di's Shamrock. This facilities water was tested in April of 2023 and found to be free of bacteria.

THIRD PARTY INSPECTION REPORTS
BACKFLOW - EXPIRED
FIRE EXTINGUISHER - EXPIRED
PROOF OF PEST CONTROL - REQUESTED



Inspected by:

Donovan Kleinberg

Date:

May 31, 2023

Received by:

This report was emailed

June 1, 2023

Date: