Missouri Department of Health & Senior Services
Bureau of Environmental Health Services
Lodging Establishment Inspection Report

FOR CENTRAL OFFICE USE ONLY	ESTABLISHMENT NUMBER

Establishment Name: Red Cedar Lodge	Name: Raj Patel ☐ Owner ☒ General Manager
Physical Address: 7036 U.S. Highway 67	City: Bonne Terre — Zip: 63628
Mailing Address: 3411 Rosener Road	City: Park Hills — Zip: 63601

County	This inspection is a(n)	Telephone	No. of Stories	No. of Rooms	Is the current lodging license displayed?
187	☐ Initial ☐ Annual ☒ Follow-up	573-358-8900	2	41	☒ Yes ☐ No ☐ N/A- new

Rooms Inspected: 15, 18, 21, 22, 28, 27, 24, 33, 48, 46

Water Supply: ☒ Private ☐ Public — Water sample taken ☐ Yes ☐ No

Wastewater: ☐ Private ☒ Public — Regulated by: ☐ DHSS ☒ DNR

Swimming Pools/Spas (check all that apply)
Indoor pool ☐ Outdoor pool ☐ Spa ☐ Pool larger than 2000 square feet ☐

Please check if the following local ordinances apply
☐ Fire Safety ☐ Electrical Wiring
☐ Plumbing
☐ Swimming Pools/Spas
☐ Fuel Burning Appliances

New Lodging Establishments ☐ N/A

Smoke detectors hardwired	☐ Yes ☐ No ☐ N/A	Swimming Pool Certified	☐ Yes ☐ No ☐ N/A
Fire alarm system installed	☐ Yes ☐ No ☐ N/A	Building Certified to National Standards or Occupancy Permit	☐ Yes ☐ No
Sprinkler system installed	☐ Yes ☐ No ☐ N/A	Historical Building	☐ Yes ☐ No ☐ N/A

Based on an inspection this day, the items marked "Out" below identify noncompliance in operations or facilities which must be corrected prior to issuance or renewal of your lodging license. Failure to comply with any time limits for corrections specified in this notice may result in revocation of your lodging license and/or prosecution. Owners may request a hearing before the Department Director upon filing a written request within ten days after receipt of this notice. (RSMo 315.005-065, 19 CSR 20-3.050)

In=In Compliance **Out=Not In Compliance, explain on additional page(s)** **NO=Not Observed** **N/A=Not Applicable**

Section A & B: Water Supply & Wastewater	In	Out	NO	N/A
1. Approved source, construction and operation	☒			
2. Complies with water quality standards	☒			
3. Chlorinator maintained and operated properly				
4. Wastewater operation and maintenance			☒	
Section C: Sanitation/Housekeeping				
1. Walls, floors and ceilings in good repair	☒			
2. Housekeeping practices and furnishings	☒			
3. Towels and bed linens clean	☒			
4. Mattresses and box springs clean	☒			
5. Pest control procedures	☒			
6. Ice machines, scoops, liners clean & protected				☒
7. Garbage storage and disposal	☒			
8. Premises maintained, plant growth controlled	☒			
Food Inspection conducted according to 19CSR20-1.025				
9. Food, equipment and single service/use				☒
10. Food protected from contamination				☒
11. Facilities to wash, rinse and sanitize				☒
12. Handwashing facilities/hygienic practices				☒
Section D: Life Safety				
1. Combustible/toxic items usage and storage			☒	
2. Building maintained to assure safe conditions	☒			
3. CO detectors hardwired, installed, good repair	☒			
4. GFCI, outlets & switches installed, good repair	☒			
5. Exit signs installed, good repair			☒	
6. Emergency lighting installed, good repair	☒			
7. Electric panel protected, labeled, good repair	☒			
Required Annual Third Party Inspections				
1. Fire Alarm System				☒
2. Sprinkler System				☒
3. Local Fire and Building Codes/Ordinances	☒			
4. Current Boiler/Pressure Vessels MDPS Certification				☒
5. Backflow Device(s) Test				☒
6. Liquid Propane Leak Test		☒		

Section E: Fire Safety	In	Out	NO	N/A
1. Textiles, hangings and mirrors	☒			
2. Fire extinguisher type, inspected, and location	☒			
3. Vertical openings fire-rated, self-closing			☒	
4. Doors, self-closing and fire-rated	☒			
5. Smoke detectors hardwired, installed, good repair	☒			
6. Evacuation route and plan, installed, available	☒			
7. Stairs and ramps, maintained, storage	☒			
8. Means of egress, number, maintained	☒			
9. Handrails and balconies maintained and appropriate	☒			
Section F: Swimming Pools/Spas				
1. Fence, gate adequate, proper closure mechanism				☒
2. Boundary line, pool depth properly marked				☒
3. Deck is clean and in good repair				☒
4. Lifesaving equipment adequate, good repair				☒
5. Pool clarity, pH, disinfectant, & temp. maintained				☒
6. Steps, ladders, and handrails installed, good repair				☒
7. Adequate ventilation				☒
8. Electrical outlets, proper protection & distance				☒
9. Records maintained and signs posted				☒
10. First aid kit available				☒
11. Lighting adequate and in good repair				☒
Section G: Plumbing/Mechanical				
1. Equipment adequate, good repair	☒			
2. Ventilation adequate, plumbing, restrooms	☒			
3. T & P relief valves adequate, good repair	☒			
4. Relief valve discharge pipes installed, adequate	☒			
5. Backflow, air gaps, no cross connections	☒			
Section H: Heating & Cooling				
1. Unvented fuel-burning appliance/space heater				☒
2. Fire resistant room or sprinkler head				☒
3. Location of heating/cooling units	☒			
4. Ventilation of appliances and utility rooms	☒			
5. Operation and condition adequate	☒			

INSPECTED BY (PRINT NAME and SIGN)	EPHS NUMBER	AGENCY	TELEPHONE
Nicholas Joggerst	1687	St. Francois County Health Center	(573)431-1947

LICENSING YEAR		DATE INSPECTED	FOLLOW UP DATE
2021 / 2022	APPROVED ☐ YES ☒ NO	6/21/2021	

RECEIVED BY (PRINT NAME AND TITLE and SIGN): Raj Patel

MO 580-0883 (6-16) Distribution: White/Owner Canary/Central Office Pink/Local Office E9.02

Time In: 10:01am Time Out: 10:59am

MISSOURI DEPARTMENT OF HEALTH & SENIOR SERVICES
BUREAU OF ENVIRONMENTAL REGULATIONS AND LICENSURE
LODGING ESTABLISHMENT INSPECTION REPORT (COMMENTS PAGE)

Establishment Name:	Physical Address:	City:
Red Cedar Lodge	7036 U.S. Highway 67	Bonne Terre

SECTION REFERENCE	OBSERVATIONS AND ADDITIONAL COMMENTS

Third party inspections
Fire extinguishers : (L and K safety done May 25, 2021)

L.P. Gas inspection: pending

NOTE: Water sample collected on June 2, 2021 and absent of E. coli and Coliforms.

Rooms 48 and 46 were inspected during this follow-up as only 8 rooms were available during the routine.

Room 46: Clean
No violations

Room 48: (clean)
No violations

NOTE: During the previous routine inspection it was noted that a sprinkler was not in the gas heated water heater. After further investigation a sprinkler was found. Additionally after consulting state head of lodging it was determined that the gas heated boiler in the unattached garage does not need an additional enclosed area but the overhead sprinkler it has now will suffice.

Approval will be given upon receipt of third party L.P. Gas inspection

Inspected by:	Nicholas Joggerst	Date: 6/21/2021
Received by:	Raj Patel	Date: 6/21/2021